## Abstract

An air trap in a blind hole is eliminated by circulating a liquid chemical along a surface-to-be-processed in substantially a given direction at all times and by setting a velocity gradient of the liquid chemical over the surface to 300/second or more, thereby eliminating the air trap in the blind hole.